








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



Position


- 1 = A 962 872 AA
3 = A 962 870 AA
4 = A 962 998 NU
5 = A 962 871 AA
6 = A 963 427 NU
7 = A 960 587 NU
8 = A 962 230 NU
10 = A 963 432 NU
11 = A 960 462 NU
12 = E 960 641 AA
15 = A 860 415 NU
16 = A 961 810 NU
18 = A 962 595 NU
21 = B 960 722 AA
23 = B 960 721 NU
24 = A 963 651 NU





CERATHERM 100
A 4813 .. A 4814 .. A 4817 ..




1016 / A 866 267
(+ A 865 612)
Made in Germany




A 4813 .. A 4814 ..



A 4817 ..



	P	bar		MIN. 0.1		MAX. 5	 Q (0.2 bar) l/min 8
	T	°C		MAX. 80		65 55	



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com

